UNINET ANNOUNCES THE RELEASE OF "NON-HP SUPPLY/CARTRIDGE INSTALLED" CHIPS

By Joe Cachia and the Technical Staff at UniNet

In collaboration with HP®'s IP & Brand Protection Team, UniNet has re-designed certain smartchips for printers identified by HP® as requiring "Non-HP" to be displayed or shown on the Status Page and Printer Display.


The October, 2013 White Paper by HP® listed specific existing printer models requiring this modification, and notified the industry that future printers require this feature as well.


We have confirmed with HP® that aftermarket chips that properly identify themselves as "Non-HP" will not lose access to functionality and will not result in a loss of features or degraded performance. The "Non-HP" message will only appear on the printer's display on first installation or warm-up; afterwards, "READY" will appear on the display.

UniNet is pleased to announce that older versions of HP printers that experience functionality loss with the "Non-HP" feature are excluded from the affected list of printers, so those chips will continue to display "Genuine HP."

At UniNet, we value the Intellectual Property Rights of others, as well as our own. Cooperation with HP® is important to avoid any brand misidentification. "Non-HP Supply" display smartchips are available for the machines shown on the following page.

Note that with this version of smartchip:





2. "Non-HP Supply/Cartridge Installed" will show on Printer Display

1. "Non-HP Cartridge" will be printed on Supplies Status Page



UNINET ANNOUNCES THE RELEASE OF "NON-HP SUPPLY/CARTRIDGE INSTALLED" CHIPS

Uninet has currently discontinued production of "Genuine HP Supply" chips as affected by the White Paper, and is working with remanufacturers and distributors to manage the proper depletion of current "Genuine" inventory.

UniNet will continue to monitor the industry for news of any changes that may further impact these products, and work with our customers to ensure a seamless transition.

Please refer to the following chart of specific models affected:

| Item | Color | # Product | # Printer |
|------|---------|---------------|--|
| 05A | black | CE505A | HP LJ P2035 / HP LJ P2055 |
| 128A | black | CE320A | HP LJ Pro CP 1525 / HP CLJ Pro CM1415 |
| 128A | cyan | CE321A | HP LJ Pro CP 1525 / HP CLJ Pro CM1415 |
| 128A | yellow | CE322A | HP LJ Pro CP 1525 / HP CLJ Pro CM1415 |
| 128A | magenta | CE323A | HP LJ Pro CP 1525 / HP CLJ Pro CM1415 |
| 25X | black | CF325X | HP LJ Enterprise 806 / HP LJ Enterprise Flow MFP 830 |
| 304A | black | CC530A | HP CLJ CP2025 / HP CLJ CM2320 |
| 304A | cyan | CC531A | HP CLJ CP2025 / HP CLJ CM2320 |
| 304A | yellow | CC532A | HP CLJ CP2025 / HP CLJ CM2320 |
| 304A | magenta | CC533A | HP CLJ CP2025 / HP CLJ CM2320 |
| 307A | black | CE740A | HP CP5225 |
| 307A | cyan | CE741A | HP CP5225 |
| 307A | yellow | CE742A | HP CP5225 |
| 307A | magenta | CE743A | HP CP5225 |
| 504A | black | CE250A | HP CLJ CP3525 / HP CLJ CM3530 |
| 504A | cyan | CE251A | HP CLJ CP3525 / HP CLJ CM3530 |
| 504A | yellow | CE252A | HP CLJ CP3525 / HP CLJ CM3530 |
| 504A | magenta | CE253A | HP CLJ CP3525 / HP CLJ CM3530 |
| 504X | black | CE250X | HP CLJ CP3525 / HP CLJ CM3530 |
| 55A | black | CE255A | HP LJ P3015 |
| 55X | black | CE255X | HP LJ P3015 |
| 85A | black | CC388A/CE285A | HP LJ P1102 / LJ Pro M1132 / LJ Pro M1212 |
| | | | <u> </u> |

If you have any questions, please contact your sales representative.

